消 防 處
防 火 組
香港九龍尖沙咀來部麻莊道1號



FIRE SERVICES DEPARTMENT, FIRE PROTECTION BUREAU,

FIRE SERVICES HEADQUARTERS BUILDING,
No. 1. Hong Chong Road,
Taim Sha Taui, East, Kowloon,
Hong Kong.
6 November 1996

FPB 316/23

本處樹號 Our Ref.:

來頭磁號 Your Ref.:

電訊掛號 Telex: 39607 HKFSD HX

2722 1915

爾文條直機 Fax: 852-3-3173969559

電話 Tel. No.:

Messrs. Jenxon Limited Rm. 2108, Hang Seng Bank North Point Bldg., 341 King's Road, North Point, Hong Kong. (Attn. Mr. Paul CHAN)

Dear Sirs,

Multiple Assemblies for Actionair Smoke/Fire and Fire Dampers

I refer to your letter ref. 6137 dated 22 October 1996 on the subject of the use of multiple assemblies arrangement of smoke/fire and fire dampers to be used in the mechanical ventilation systems.

After scrutinising the submitted document, I have no objection on the use of 'Actionair' Fire/Shield, Hot/Shield and Smoke/Shield dampers in mechanical ventilating systems based on the compliance of the following assessment report and the 'no objection' letters issued for the single module of the appropriate type fire dampers issued by Fire Services Department:

Testing Laboratory

Loss Prevention Council (LPC)

Assessment report

LPC Project 88375 dated 11 October 1996

Product tested

'ACTIONAIR' Fire/Shield, Hot/Shield and Smoke/Shield

Fire Dampers

Manufacturer

Actionair

Construction

As detailed in the following drawings:

AA/F/4148, dated 30/9/1996 AA/F/4149, dated 30/9/1996 AA/F/4150, dated 30/9/1996 AA/F/4151A, dated 11/10/1996 AA/F/4152, dated 30/9/1996

Installation method:

As appeared in the Manufacturer's catalogue or other methods

endorsed by the manufacturer.

Standards tested

BS 476: Part 22: 1987

Result obtained

Integrity:

120 minutes

Yours faithfully,

(WONG Pak-wing)

for Director of Fire Services